


SECRET-CONTROL/US OFFICIALS ONLY



Sketch 1:


Plan of the Manfred-
Walss Works in Cseppel

Scale 1:500

Legend:

- 1 Slag transport (ground floor)
- 2 3 high-pressure boilers (100 atmospheres)
- 3 Pulverizer fans (ground floor)
- 4 Feed-water purification installation
- 5 Feed-water pumps (125 atmospheres)
- 6 Office
- 7 Condensers
- 8 High-pressure turbine (13,500 kw)
- 9 Three low pressure turbines (5,000 kw each)
- 10 Low-pressure boilers (66 flue boilers)
- 11 Coal conveyor to coal bunker in third floor

Sketch 2:


Vertical Section Through Boiler House

Legend:


- 1 Coal bunker
- 2 Boiler
- 3 Control turbines (Schaltturbinen) (second floor)
- 4 Cooling devices and fans - (ground floor)
- 5 Bomb-proof basement

Layout Sketch of the Laboratory of the Weiss Manfred Works


First floor



Second floor



Third floor



Scale 1:500


Legend continued:

- 12 Files office
- 13 Library
- 14 Head of chemical laboratory
- 15 Laboratory
- 16 Chemical laboratory
- 17 Preparation room
- 18 Toilet
- 19 Russian acceptance office
- 20 Inner gallery
- 21 Machines testing endurance
- 22 Storeroom

CONFIDENTIAL

~~SECRET CONTROL/US OFFICIALS ONLY~~Layout Sketch of Steel Foundry of the Weiss Manfred WorksLegend:


1. Operating office.
2. Plant forge
3. Shop for cleaning ingots and storage space.
3. 4 open-hearth furnaces
5. Charging platform for open-hearth furnaces
6. Auxiliary installations (fans, forge for test pieces, oil tanks)
7. Power Plant
8. Forge
9. Ingot molds
10. Two electric furnaces system Héroult
11. One high-frequency furnace
12. Office
13. Steel foundry I
14. One electric furnace
15. Office
16. Lime, sand, coke dump auxiliary material dump
17. Dump for boxes of dolomite
18. Foundry head's office
19. One electric furnace
20. Steel foundry II
21. Office
22. Laboratory
23. Coal bunker
24. Gas generators
25. Office



CONFIDENTIAL

~~SECRET CONTROL/US OFFICIALS ONLY~~


CONFIDENTIAL/AMC

~~SECRET - CONTROL/US OFFICIALS ONLY~~Layout Sketch of Machine Tools Plant of the Weiss Manfred Works*not to scale***Legend:**

- 1 Low-pressure plant
- 2 Bicycle factory
- 3 Machine-tool manufacturing plant.
- 4 Material testing shop.
- 5 Cartridge-case factory.
- 6 Bunker No. 4
- 7 Precision mechanics department.
- 8 Enameling works
- 9 to Management
- 10 to No. III entrance
- 11 Tin-plate rolling mill

CONFIDENTIAL~~SECRET - CONTROL/US OFFICIALS ONLY~~

SECRET CONTROL
U. S. OFFICIALS ONLY



① Weiss-Manfred Works

CONTROL
U. S. OFFICIALS ONLY

CONFIDENTIAL